



FILM TYPE _____

COATING
IDENTIFICATION _____

FILM TEST: YES ____ NO ____ SENSITOMETRY: YES ____ NO ____

Example:




DESCRIBE YOUR ROLL: (Where to TEST/place SENS)

HAS Images, Inc.
937-222-3856
FAX 937-222-2443

**UNPROCESSED FILM
DO NOT EXPOSE TO:**




Radiation



Light



X-Ray



Heat

HAS Images, Inc.
937-222-3856
FAX 937-222-2443

From:



Photographic Materials



HANDLE with CARE

937-222-3856

HAS Images, Inc.


136 North St. Clair Street, Suite 300
Dayton, OH 45402

Revised 12/23/99 SAMPLE FILM LABELS FOR B/W (PROCESSING TO GAMMA)

FILM TYPE Agfa Pan 200P ZP-1
COATING IDENTIFICATION
FILM TEST: YES X NO SENSITOMETRY: YES X NO


FILM TYPE 2424 B/WIR ZR-1
COATING IDENTIFICATION
FILM TEST: YES X NO SENSITOMETRY: YES X NO

Example:



HRS Images, Inc.
937-222-3856
FAX 937-222-3443

Example:




HRS Images, Inc.
937-222-3856
FAX 937-222-3443

SAMPLE FILM LABEL FOR COLOR (NORMAL PROCESS)

FILM TYPE 2445 Aero Neg. & SO-134 Color IR
COATING IDENTIFICATION
FILM TEST: YES NO X SENSITOMETRY: YES X NO

Example:



HRS Images, Inc.